


Just as in CAD, it would be nice and very handy, if the CAM layer visibility also implies switching that toolpath On or Off for 3D simulation and CAM Export. Testing and debugging is becomes far more easier



The image shows a vertical list of toolpaths in a CAM software interface. Each item has a small circular icon to its left, which is currently turned off (represented by a grey circle with a white dot). The list includes:

Toolpath Name	Count	Type
Drill 16	12	Drill
Drill 17	12	Drill
Drill 18	12	Drill
Drill 19	12	Drill
Drill 20	12	Drill
Profile 1	1	Profile
Profile 2	1	Profile
Profile 3	1	Profile
Profile 4	1	Profile
Profile 5	1	Profile
Profile 6	1	Profile
Profile 7	1	Profile